
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —							
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-178	Smoke	7/21/2009	ADS/TM	S13AA_021MH	Dry	Yes	850.79



Smoke and Dye Testing Summary

High Level Sewershed

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-178	Smoke	7/21/2009	ADS/TM	S13AA_021MH	Dry	Yes	850.79

lated Pipes ————————————————————————————————————						
Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)		
S13AA_002G1	S13AA_002MH	S13AA_009MH	72.4332	8		
S13AA_009G1	S13AA_009MH	S13AA_003MH	100.426	8		
S13AA_003G1	S13AA_003MH	S13AA_021MH	324.762	8		
S13AA_021G1	S13AA_021MH	S13AA_024MH	172.079	8		
S13AA_018G1	S13AA_018MH	S13AA_021MH	181.094	8		

Observations & Photos